



OR5 Push Rod Replacement

| | |
|-----------------------|---|
| Classification | Mandatory |
| Applicability | OR5 components delivered between the beginning of May 2001 and the end of February 2002 |
| Compliance | Before the next flight |

Introduction

It has been found that a batch of OR5 items were manufactured from a soft grade of aluminium which is visually virtually identical to the correct grade. The applicability time range covers this batch with a safety margin.

Verifying applicability

Remove the OR5 from the aircraft, and place it on a block of wood approximately 12mm (½") thick on a flat table, positioning it such that the parallel section is on the block and half of its overall length is overhanging the block.

Push the free end down until it makes contact with the table. After release a correct OR5 will spring back to its correct shape. If it remains bent it is faulty and should be discarded.

Action

If the item is faulty, install the free replacement supplied.